

Amo.

Fault Report

Customer Name Am Group	Date: 10/3/26
Customer Reference: GBC113	Fitter Amo
Salesperson: Steven	Salesperson called: Yes/No
Fault Description: continuous chain on blind 3 too long should be 1000	
Action to correct: cut chain down to 1000	
Problem fixed on site: Yes /No	
Further action required: return to site and cut chain down to 1000	