

Fault Report

Customer Name PORTEOUS	Date; 18/03/26
Customer Reference: 26968	Fitter KEVIN MICHAEL
Salesperson: KEVIN	Salesperson called: Yes/No
Fault Description: Bedroom blind measured too big should be 1170mm Recess	
Action to correct: Cut bedroom blind blind down to 1170mm Recess.	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes cut down blind & return to fit.	