

# Fault Report

Customer Name COOPER	Date; 30/3/26
Customer Reference: 27033	Fitter MICHAEL
Salesperson: KEVIN	Salesperson called: Yes/No
Fault Description: Living Room (R) ordered as RH instead of LH	
Action to correct: Reorder blind with RH controls	
Problem fixed on site: Yes (No)	
Further action required: Yes, reorder & return to fit.	