

Fault Report

Customer Name MARINE ELECTRICAL	Date; 03/04/26
Customer Reference: GBC 133	Fitter MICHAEL
Salesperson: KEVIN	Salesperson called: Yes/No
Fault Description: Mismeasure on blind NO 2 Back office (R)	
Action to correct: Reorder or cutdown to 510mm recess	
Problem fixed on site: Yes (No)	
Further action required: Yes remake & return to fit	