

Fault Report

Customer Name NORRIE	Date; 16/04/26
Customer Reference: 26829	Fitter MICHAEL
Salesperson: KEVIN	Salesperson called: Yes/No
Fault Description: 2 x slats missing for bedroom (2)	
Action to correct: send up 2 slats @ 1040mm recess	
Problem fixed on site: Yes/No	
Further action required: Yes make 2 x new slats @ 1040mm 1040mm Recess.	