

SB 6132

WHEATER

Fault Report

Customer Name:	Date: 7/Nov/23
Customer Reference: SB6132 Wheeler	Fitter: Dylan
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Sunwood Wooden Blind	
Fault Description: Bracket overhang, depth of Blind over hangs window, customer refused! doesn't want overhang	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: * David going back 20/11 *	