

SB 6010
MCDONALD / RJ

Fault Report

Customer Name: Mcdonald	Date: 1/11/23
Customer Reference: 6010 Salesperson: David	Fitter: David Salesperson called: Yes/No
Blind Type and number: Intu, venetian	
Fault Description: Hall venetian made in wrong slats	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: New hallway (side window) blind made in 1872 ⁹⁷⁷¹ slat. Phone me for info if needed	