

SB 5988  
SMITH/R.

# Fault Report

Customer Name: Smith Customer Reference: 5988	Date: 8/11/23 Fitter: David
Salesperson:	Salesperson called: Yes/No
Blind Type and number: Kitchen left roller	
Fault Description:  Faulty spring in the roller (wont keep it tension)	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:  New spring needed	