

SB 6040

KENNY/R.

Fault Report

Customer Name: <u>kenney</u>	Date: <u>17 NOV/23</u>
Customer Reference: <u>6040</u>	Fitter: <u>Dylan</u>
Salesperson: <u>Graeme</u>	Salesperson called: <u>(Yes)</u> No
Blind Type and number: <u>wooden</u> <u>873 / 1423 (white with tapes)</u>	
Fault Description: <u>cord lock missing part</u>	
Action to correct: <u>Replace blind or replace missing cordlock.</u>	
Problem fixed on site: Yes <u>(No)</u>	
Further action required:	