

SB 6668

HORNELL / R.

BM6874R

Fault Report

Customer Name: Hornell	Date: 21/02/24
Customer Reference: 6668	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Lounge vertical	
Fault Description: Slats wrong size(mismeasure)	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: New slats at at 1755x1553	