

SB 6653

STRAWMAN/R

Thur 4<sup>th</sup> April

BM 6827R1

# Fault Report

Customer Name: <del>David</del> STRAWMAN	Date: 25/03/24
Customer Reference: 6653	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Vertical lounge back	
Fault Description:  Unable to find original slats to go with the extra slats that were made	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:  New slats needed	