

SB 6469,
SCULLION

Fault Report

Customer Name: Scullion	Date: 8/5/24
Customer Reference: 6469	Fitter: Ross
Salesperson: David	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: All 3 rollers	
Fault Description: Rollers too narrow	
Action to correct: David to go back out to see customer	
Problem fixed on site: Yes/No	
Further action required: * David going back 15/5 *	