

SB 6409

Mackenzie IR

SB 6966R

# Fault Report

Customer Name: Mackenzie	Date: 12/04/24
Customer Reference: 6409	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: lounge roller	
Fault Description:  Blind is damaged pictures sent in	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:  New lounge blind needed	

