

SB 6517

MCDERMOT

Fault Report

Customer Name: McDermott	Date: 29/05/24
Customer Reference: SB 6517	Fitter: Ross
Salesperson: David	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: Vertical	
Fault Description: Hangers on verts snapped	
Action to correct: Can we send hangers?	
Problem fixed on site: Yes/No	
Further action required: *Graeme went to see customer - going back 4/6 to replace 10 hangers.	