

SB 4032
FORSYTH / R

SB 4375R

Fault Report

Customer Name: Forsyth	Date: 1-5-24
Customer Reference: 4032	Fitter: DAVID
Salesperson: MARK	Salesperson called: Yes/No
Blind Type and number: ROLLA	
Fault Description:	
Action to correct: FAULT MOTOR NOT CHANGING OR RESETTING	
Problem fixed on site: Yes/No	
Further action required: NEW MOTOR SOMFY ROLL UP 28 RTS	