

SB 7059R

SB 6476
SPENCE/R.

Fault Report

| | |
|---|---|
| Customer Name: Spence | Date: 8/5/24 |
| Customer Reference: 6476 | Fitter: Ross |
| Salesperson: office / cust | Salesperson called: Yes/No <input checked="" type="radio"/> |
| Blind Type and number: Vertical - slats only | |
| Fault Description: Slats have been ordered as recess - should have been hem to hem | |
| Action to correct: Re-make slats at hem to hem size 1372mm. | |
| Problem fixed on site: Yes/No | |
| Further action required: | |