

SB 4032  
FORSYTH / R  
ON 437SRI

# Fault Report

Customer Name: FORSYTH	Date: 20-5-24
Customer Reference: 4032	Fitter: DAVID
Salesperson:	Salesperson called: Yes/No
Blind Type and number: MOTOR	
Fault Description: WRONG MOTOR SENT OUT RTS 28 ROLLUP SENT OUT	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: RTS 24 ROLL UP IS NEEDED	

