

SB 6523
ANDERSON/R

Fault Report

SB7 08412

Customer Name: Anderson	Date: 7/6/24
Customer Reference: 6523	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Vertical track	
Fault Description: Blind has been made shorter than asked for (has been made at 1760)	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: New blind at 2050 recess size as on original ticket	