

VERIFIED BY PIN
PLEASE PRINT NAME OF APPLICANT

SB 6331

HAMILTON/R

Fault Report

SB7079R

Customer Name: Hamilton	Date: 10/6/24
Customer 4 Reference: 633 6331	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Front top room roller	
Fault Description: Customer has said that she asked for the faux wood in that room instead of a roller so it's the wrong blind.	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: New blind needed in 35mm serene fauxwood for front bed top	

