

SB 6744
MUNRO/R

Fault Report

FITTER NAME: David	FITTING DATE: 4/11/24
Customer Name: Munro	
Customer Ref: 6744	
Salesperson: RONNIE	Salesperson called: Yes/No
Blind Type and number: Shutter	
Problem fixed on site: Yes/No	
Fault Description The gap is too big to caulk at the side of the shutters	
Action to Correct: 2 Cover strips needed at 5x50x1882 (Timless white) <i>Balmoral wood</i>	