

SB 6781  
MCDONALD / R

# Fault Report

SB 7 249R

<b>FITTER NAME:</b> David		<b>FITTING DATE:</b>	
<b>Customer Name:</b> Mcdonald			
<b>Customer Ref:</b> no paperwork provided 6781			
<b>Salesperson:</b>		<b>Salesperson called:</b> Yes/No	
<b>Blind Type and number:</b>  Faux wood venetian front bedroom left			
<b>Problem fixed on site:</b> Yes/No			
<b>Fault Description</b>  Tilt cord has snapped and is too short to operate the blinds now.  1230 drop .			
<b>Action to Correct:</b>  New tilt cord mechanism needed with grey cord			

C/C  
Cheque

every day.