

SB 6909

RIGBY/R

SB 739SR

# Fault Report

FITTER NAME: David

FITTING DATE: 9/10/24

Customer Name: Rigby

Customer Ref: 6909

Salesperson: RONNIE

Salesperson called: Yes/No

Blind Type and number:

Kitchen roller

Problem fixed on site: Yes/No

Fault Description

The fabric has started to curl in at each end of the blind.

Action to Correct:-

Pictures have been emailed in for a decision to be made on what to do with it.