

SB 7038

CAMERON/K

Fault Report

ON 75612

FITTER NAME: David	FITTING DATE: 20/11/2024
Customer Name: Cameron	
Customer Ref: 7038	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number: Liv left pf	
Problem fixed on site: Yes/No	
Fault Description Blind has been measured the wrong size.	
Action to Correct:- Blind to be cut down to 648 width	

