

SB 7715

TAYLOR/RT

Fault Report

ON 85969
on Rainbow

FITTER NAME: David	FITTING DATE: 28/02/2025
Customer Name: Taylor	
Customer Ref: 7773	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number: Perfect fit roller 2	
Problem fixed on site: Yes/No	
Fault Description Top right hand corner piece is broken and doesn't stay on the frame	
Action to Correct: PART THAT JOINS THE FRAMES + SPRING GOES INTO New corner piece needed and will fit it on site. It's the side that the spring goes into.	