

Fault Report

SB 7557
PHILLIPS/R.

ON 87792R

FITTER NAME: David

FITTING DATE: 7/4/2025

Customer Name: Phillips

Customer Ref: 7557

Salesperson: Ronnie

Salesperson called: Yes/No

Blind Type and number:

Perfect fit venetian 1&2

Problem fixed on site: Yes/No

Fault Description

The plastic cut outs for the handles don't work as the spindles are not long enough on the handles

Bottom and Top of Handle - Needs cut.

Action to Correct:- L Blind - R Leg - to bottom of handle
480 and to top of handle 525.

A right sided piece of frame with a cut out on the frame for blind 1
A left sided piece of frame with a cut out on the frame for blind 2

Both cut outs to be the same place as original order but just not the plastic cut out.

R Blind - L leg - to bottom of handle
454 and to top on handle 522

