

Fault Report

Customer Name: MCDONALD	Date: 2-6-25
Customer Reference: 6950	Fitter: DAVID
Salesperson: RONNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: Bed R Roller	
Fault Description: BLIND NOT STAYING IN POSITION	
Action to correct: New 40mm roller SIDE WINDER NEEDED	