

# Fault Report

Customer Name: SIMPSON	Date: 2-6-25
Customer Reference: 7483	Fitter: DAVID
Salesperson: RONNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: FBER PF ROLLER	
Fault Description: <del>ALL OTHER</del> FBER PF HAS BEEN MADE CHAIN OPERATED <del>OTHER</del> BUT ALL OTHERS HAVE BEEN MADE TENSIONED ALSO TOP LEFT CORNER JOIN DAMAGED	
Action to correct: CUSTOMER WANTS THE BLIND TO BE TENSIONED SO THE SAME AS THE REST. BLIND IS IN SCOTBLINDS TO GET PICKED UP.	