

SB 7485
Forrester 1A

Fault Report

Customer Name: Forrester	Date: 30-6-25
Customer Reference: 7485	Fitter: DAVID
Salesperson: RONNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: PF PLEAT NUMBER 10 PATIO LEFT R	
Fault Description: NO HOLES PUNCHED IN ONE SIDE OF THE FRAME	
Action to correct: BLIND AT SCOT BLINDS TO GO BACK TO RAINBOW TO GET HOLES PUNCHED IN FRAME	