

Fault Report

Customer Name: IRVINE	Date: 25/8/25
Customer Reference: 7245	Fitter: DAVID 19/8/25
Salesperson: RONNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/NO	
Blind Type and number: Pole Room R123 POC VERTICALS. HOT TUB ROOM R123	
Fault Description: MADE TOO LONG	
Action to correct: REMAKE SLOTS	

Fault Report

Customer Name: IRVINE	Date: 25/8/25
Customer Reference: 7245	Fitter: DAVID 18/8/25
Salesperson: KENNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No <input checked="" type="checkbox"/>	
Blind Type and number: PATIO R ROBBANT ON GROUND WHEN SUN IS OUT PATIO L BROKEN SLIT	
Fault Description: PATIO R. ROBBANT ON GROUND WHEN SUN IS OUT PATIO L BROKEN SLIT	
Action to correct: REDUCE SIZE BY 10MM PATIO R. NEW SLIT REQUIRED PATIO L	

