

SCOT BLINDS

SB 7829
CHRISTIE 1R

Fault Report

Customer Name: <u>CHRISTIE</u>	Date: <u>7829-12-25</u>
Customer Reference: <u>7829</u>	Fitter: <u>DAVID</u>
Salesperson: <u>LOUIE</u>	Salesperson called: <u>Yes/No</u>
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: <u>Yes/No</u>	
Blind Type and number: <u>LH</u> <u>LIV FRONT SHUTTER RH FRAME</u>	
Fault Description: <u>LH</u> <u>RH FRAME MARKED.</u> <u>CUSTOMER ALSO WANTING COVER STRIPS FOR BACK OF THE SHUTTERS</u>	
Action to correct: <u>NEW RH FRAME FOR LIV FRONT</u> <u>5 x 35 x 1250 (2 needed)</u> <u>5 x 35 x 1243 (2 needed)</u> <u>5 x 35 x 1097 (2 needed)</u>	

ORDER TOTAL = £2180.00
DEP PD = 3/9/25.

