

SCOT BLINAS

SB 7908
Malcolm IR.

Fault Report

Customer Name: MALCOLM	Date: 11-2-26
Customer Reference: 7908	Fitter: DAVID
Salesperson: RONNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: SHUTTER	
Fault Description: GAP AT THE TOP OF THE SHUTTER	
Action to correct: NEEDS COVER STRIP AT 5 x 2355 x 50	

ORDER TOTAL = €1185.00
DEP PO = 13/10/25.

