

SCOT BLINAS

Fault Report

Customer Name: <u>DUNNECY</u>	Date: <u>25-2-26</u>
Customer Reference: <u>8077</u>	Fitter: <u>DAVID</u>
Salesperson: <u>RONNIE</u>	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: <u>CURTAIN TRACK</u>	
Fault Description: <u>TRACK wrong size + BENDS</u> <u>CURTAIN FITTED BUT NEEDS NEW TRACK</u>	
Action to correct: <p>144° angle 133° angle 138° angle 141° angle 750 1100 740 810 850</p> <p>New TRACK 4 BENDS TOTAL LENGTH 4380</p>	

ORDER TOTAL = £1189.00
DEP PD = 18/12/25.