

SB 4191

Abreu R

SCOTBLINDS - FAULT SHEET

CUSTOMER DETAILS:

ID: SB4191 Abreu

NAME:

ADDRESS:

TELEPHONE NO:

EMAIL:

DATE REPORTED: 12.5.22

ISSUE REPORTED:

New fitted kitchen installed
tap stops shutter door opening

REMEDIAL ACTION REQUIRED:

change door layout to
LLR
kitchen window size 1746x1141

* Forward To Graeme *

OFFICE USE

CUSTOMER CONTACT LOG: