

SB 5420
MALYN

Fault Report

Customer Name: MALYN	Date: 21-2-23.
Customer Reference: MALYN SB5420	Fitter: MARK E
Salesperson: MARK E	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: BED 1 + SNUG	
Fault Description: SLATS DAMAGED ON BED 1 + SNUG BLIND. LOUNGE PELMET NEEDS REPLACES.	
Action to correct: ORDER 3x PELMETS FOR LOUNGE 800 X 2. RE ORDER BLIND FOR SNUG + BED 1 800 995 .	
Problem fixed on site: Yes/No	
Further action required:	