

# Fault Report

Customer Name: EVANS	Date: 10/6/22
Customer Reference:	Fitter: GRAEME
Salesperson: GRAEME	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: LIGHT GAP AT TOP + BOTTOM RAILS OF DOOR PANEL.	
Action to correct: CAN WE ATTACH A STRIP OF CARD TO RAILS TO CLOSE LIGHT GAP.	
Problem fixed on site: Yes/No	
Further action required: 2 x card required Double sided tape. W-800 W-826.	