

Rain 6510
Masterson / R

Fault Report

Customer Name: MASTERSON	Date: 3/13/22
Customer Reference: 6510	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: VERTICAL 1 + 2	
Fault Description: BLIND 1 MISSING 9 SLATS BLIND 2 SLATS BEEN MADE TOO LONG	
Action to correct: NEW SLATS AT SIZES GIVEN	
Problem fixed on site: Yes/No	
Further action required:	