

Fault Report

Customer Name: Black	Date: 23/7/22
Customer Reference: 6730	Fitter: Cameron
Salesperson: David	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Roller	
Fault Description: Blind to small on width	
Action to correct: Remeasured states blind New sizes 940mm wide	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required:	

part paid
£10.00