

Fault Report

Customer Name: STEWART	Date: 29-7-22
Customer Reference: 6607	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: 2+3	
Fault Description: SIDE CHANNELS MISSING BOTTOM ONE ON MIDDLE SHUTTER + RIGHT SIDE ON RIGHT SHUTTER	
Action to correct: to NEW SIDE CHANNELS NEEDED	
Problem fixed on site: <input checked="" type="checkbox"/> Yes/No	
Further action required:	