

Fault Report

Customer Name: Neil	Date:
Customer Reference: 4331	Fitter: CAMERON
Salesperson: CAMERON	Salesperson called: Yes/No
Blind Type and number: 1 roller	
Fault Description: roller Roller 2 is fraying bad on both sides of blind	
Action to correct: Request remake	
Problem fixed on site: Yes/No <input checked="" type="radio"/> No	
Further action required:	