

Fault Report

Customer Name: CARNAHAN	Date: 6-10
Customer Reference: 7014	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: 1	
Fault Description: SLATS HAVE BEEN MADE TO WRONG SIZE MADE LONGER THAN ASKED FOR.	
Action to correct:	
Problem fixed on site: Yes /No	
Further action required: New SLATS AT 1410	