

Fault Report

Customer Name: Spalding	Date: 12/10/22
Customer Reference:	Fitter: Cameron
Salesperson: LL	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: 2 Rollers	
Fault Description: Centre roller cutdown should be @ recess size. Blind 3 Returned to be recovered	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	