

Ed 4314

Bremner/R

Fault Report

Customer Name: BRENNER	Date: 21-10-22
Customer Reference: ED 4314	Fitter: GILFENE
Salesperson: CAMERON	Salesperson called: Yes/NO
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: BLIND 1 + 2	
Fault Description: CUSTOMER STRUGGLES TO HOLD CORD AT THE ANGLE REQUIRED TO LOWER VENETIAN. CURRENTLY HAS 4 CORDS.	
Action to correct: CAN WE REMAKE WITH 3 CORDS AND 1 CHILD SAFETY BOX.	
Problem fixed on site: Yes/No	
Further action required:	