

Fault Report

Customer Name: NEILL	Date: 10-01-23
Customer Reference: 7251	Fitter: GARY
Salesperson: GARY	Salesperson called: Yes /No
Blind Type and number: SLATS ONLY 1	
Fault Description: ORDER RECESS INSTEAD OF HEM TO HEM	
Action to correct: REWORK SLAT SIZE 1170 HEM TO HEM 26 IN TOTAL.	
Problem fixed on site: Yes/No	
Further action required:	