

ED 4718
PORTER.

Fault Report

Customer Name: PORTER	Date: 3-5-23
Customer Reference: 4718	Fitter: DAVID
Salesperson: GARY	Salesperson called: Yes/No
Blind Type and number: 1 Roller	
Fault Description: BLIND MADE WRONG SIZE AS TO WHAT HAS BEEN ASKED FOR. MADE AT 528 INSTEAD OF 585	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: New BLIND AT 585	