

FD 4724 LAIRD

Customer Name: Laird	Date: 31-05-23
Customer Reference: 4727	Fitter: Gary
Salesperson: Gary	Salesperson called: Yes/No —
Blind Type and number: Vertical Headrails	
Fault Description: Blind 2 and 3 are controlled incorrectly	
Action to correct: Remake blind 2 as a Right-hand control with a left stack Remake Blind 3 as a left-hand control with a right stack	
Problem fixed on site: No	
Further action required:	

# Fault Report