

ED 4733
MCKAY/R.

Fault Report

Customer Name: MCKAY	Date: 21-6-23
Customer Reference: 4733	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: Roller 3	
Fault Description: CUSTOMER WANTS THE BLINDS WIDER TO CUT OUT MORE LIGHT	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: NEW BLIND 30MM WIDER JUST THE MATERIAL NEEDED AS WILL USE SAME FITTING OR MOTOR	
ALL ROLLERS ARE NOT PROGRAMMING CORRECTLY EITHER BEFORE THAT	