

RAIN 7521
DELANEY/R

Fault Report

Customer Name: Dalaney	Date:07/07/2023
Customer Reference: 7521	Fitter: Gary
Salesperson: Gary	Salesperson called: Yes/No
Blind Type and number: 1 Roller	
Fault Description: Bedroom Roller too small	
Action to correct: Re-make at 1770 x 1200 (FH 2000) RH control	
Problem fixed on site: Yes/No	
Further action required:	