

EO 4769

VAN DER VELDEN

Fault Report

Customer Name: VAN DER VELDEN	Date: 19/07/2023
Customer Reference: 4769	Fitter: GARY
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: ALL PF ROLLERS	
Fault Description: ALL PERFECT FIT ROLLERS HAVE HOLES IN FABRRIC	
Action to correct: RE-MAKE ALL 4 PERFECT FITS	
Problem fixed on site: Yes/No	
Further action required: BLIND 1 - LH CHAIN - CHAIN FULL LENGTH OF DROP BLIND 2 - FR SIZE (813 X 996) TENTIONED BLIND 3 - RH CHAIN - CHAIN FULL LENGTH OF DROP BLIND 4 - AS IS ON SYSTEM Blind 2 was been made chain control TRANSFERED TO TRADE TO REMAKE.	

ED 4769
VAN DER HEIDEN

Customer Name: Van Der Heiden	Date: 30-06-23
Customer Reference: 4769	Fitter: Gary
Salesperson: David	Salesperson called: Yes/No No
Blind Type and number: Perfect fit Mismeasure	
Fault Description: Frame short on height	
Action to correct: Please remake blind 2 at 813 x 996	
Problem fixed on site: No	
Further action required:	

Fault Report

