

7796 Connor/k
FR

Fault Report

Customer Name: Connor	Date: 7/12/23
Customer Reference: 7796	Fitter: Dylan
Salesperson: CARY	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Blind Type and number: Bed R (BLIND1)	
Fault Description: Blind has been measured too large	
Action to correct: re order blind @ 1845 x 1805	
Problem fixed on site: <input checked="" type="radio"/> Yes / <input type="radio"/> No	
Further action required: Yes.	