

✓ RAIN 7822
HILL/R.

Fault Report

②

Customer Name: HILL	Date: 12-12-23
Customer Reference: RAIN HILL 7822	Fitter: GRAEME
Salesperson: GRAEME	Salesperson called: Yes/No
Blind Type and number: LIV M.	
Fault Description: CORDS AT DIFFERENT HEIGHTS FROM OTHER.	
Action to correct: NEED LOWER TILT + LIFTING CORDS.	
Problem fixed on site: Yes/No	
Further action required:	